03500.017385 MAY 2 7 2005

PATENT COPE

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:		)	
		:	Examiner: Phat X. Cao
YUKIH	IRO HAYAKAWA ET AL.	)	
		:	Group Art Unit: 2814
Appln. 1	No.: 10/615,288	)	
		:	A
Filed: .	July 9, 2003	)	Certificate
<b>.</b>		:	JUN 0 6 2005
For:	SEMICONDUCTOR DEVICE AND	)	
	LIQUID JETTING DEVICE USING THE	:	of Correction
	SAME	)	
		:	
U.S. Pat	tent No.: 6,867,457 B2	)	
		:	
Issued:	March 15, 2005	)	May 26, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

## CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Elizabeth F. Holowacz Attorney for Patentees

Registration No. 42,667

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

502427v1

### UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. :

6,867,457 B2

DATED

March 15, 2005

INVENTOR(S) :

YUKIHIRO HAYAKAWA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"1221720 A2" should read --1 221 720 A2--;

"0574911 A2" should read --0 574 911 A2--;

"2309589 A" should read -- 2 309 589 A--.

#### SHEET 20

FIG. 23, "Pusb" should read -- Psub--..

#### COLUMN 1

Line 33, "a" should read --an--.

#### **COLUMN 5**

Line 46, "this" should read --these--; and

Line 49, "length-of" should read --length of--.

#### COLUMN 7

Line 36, "boarder" should read --border--;

Line 57, "deice" should read --device--.

#### COLUMN 10

Line 34, "using," should read --using--.

#### MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,867,457 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

502427v1

No. of add'l. copies

@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

6,867,457 B2

**DATED** 

March 15, 2005

INVENTOR(S) :

YUKIHIRO HAYAKAWA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 11

Line 11, "not" should read --not be--.

#### COLUMN 12

Line 3, "formed" should read --formed and--.

#### **COLUMN 16**

Line 20, "device-according" should read --device according--.

#### **MAILING ADDRESS OF SENDER:**

PATENT NO. <u>US 6,867,457 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

502427v1

**■**> \_\_\_\_